



Your INSPECTION REPORT

Vehicle Description: **Date of Inspection:** 3/11/2013
Full VIN: 2T3BF4DV3BW083538 **Year:** 2011 **Engine Cylinders:** 4
Mileage: 22742 **Make:** TOYOTA **Engine Liters:** 2.5L
Transmission Type: Automatic **Model:** RAV4 **Engine Type:** Gas

| Inspection Area | Overall Rating |
|------------------------------|----------------|
| Body | Good |
| Glass | Excellent |
| Wipers | Excellent |
| Tires & Wheels | Excellent |
| Interior Items | Excellent |
| Gauges | Excellent |
| Audio System | Excellent |
| Carpet & Upholstery | Fair |
| Trunk | Excellent |
| Electrical System | Excellent |
| Under Hood | Good |
| Road Test | Excellent |
| Additional Inspection Points | Excellent |



Exterior

BODY

OVERALL RATING: GOOD

| | | | |
|-----------------------------------|---------------------------------------|--------------------|------------------|
| Front | Repainted | Rear | Repainted |
| Hood | Repainted | Roof | OK |
| Bumpers | Scratch 0-1"/ Chip 0-1" | Trim | OK |
| Left front | OK | Right front | OK |
| Left rear | Repainted/ Previously Repaired | Right rear | Repainted |
| Left doors | Repainted | Right doors | Repainted |
| Overall Condition of Paint | GOOD | | |

GLASS

OVERALL RATING: EXCELLENT

| | | | |
|-------------------|----|--------------------|----|
| Windshield | OK | Rear window | OK |
| Left front window | OK | Right front window | OK |
| Left rear window | OK | Right rear window | OK |

TIRES AND WHEELS

OVERALL RATING: EXCELLENT

| | | | |
|--------------------|-----------|---------------------|------|
| Condition of tires | EXCELLENT | Condition of wheels | GOOD |
|--------------------|-----------|---------------------|------|

Comments on Tires and Wheels:

All tires are practically new in condition 9-10/32". The steel wheels are in good condition

WIPERS

OVERALL RATING: EXCELLENT

| | | | |
|-------------------------|----|------------------------|----|
| Front wipers | OK | Rear wipers | OK |
| Front wiper blades | OK | Rear wiper blades | OK |
| Front windshield washer | OK | Rear windshield washer | OK |

Comments on Exterior:

This is a FLOOD vehicle- please call Charlie, your inspector for this Toyota, at 215-480-1536 for further details. There has been previous paint work on most panels of this vehicle. The color match and quality is very good. Body work to the left rear quarter panel could be better but imperfections are only noticeable up close. No current visible rust exists on the body or frame however as with any flood vehicle that is subject to change daily....

Interior

INTERIOR ITEMS

OVERALL RATING: EXCELLENT

| | | | |
|-------------------------|----|----------------|----|
| Glove box | OK | Head rests | OK |
| A/C cooling performance | OK | Door panels | OK |
| Heater operation | OK | Dash pad | OK |
| Hood release | OK | Vanity mirrors | OK |
| Cigarette lighter | OK | | |

GAUGES

OVERALL RATING: EXCELLENT

| | | | |
|-------------|----|--------------|--------------|
| Speedometer | OK | Oil pressure | NOT REPORTED |
| Tachometer | OK | Amp meter | NOT REPORTED |
| Temperature | OK | | |

AUDIO SYSTEM

OVERALL RATING: EXCELLENT

| | |
|-----------|----|
| Radio | OK |
| CD player | OK |

CARPET AND UPHOLSTERY

OVERALL RATING: FAIR

| | | | |
|-----------------|-----------------------|----------------|------------|
| Front seats | Stain 3-6" | Rear seats | Stain 3-6" |
| Front carpeting | Stain 3-6"/ Tear 3-6" | Rear carpeting | Stain 3-6" |
| Headliner | OK | | |

TRUNK

OVERALL RATING: EXCELLENT

| | | | |
|-----------|----|------------|----|
| Carpeting | OK | Spare tire | OK |
| Tools | OK | Floor pan | OK |
| Jack | OK | | |

ELECTRICAL SYSTEM

OVERALL RATING: EXCELLENT

| | | | |
|----------------|----|------------------|--------------|
| Head lights | OK | Turn signals | OK |
| Tail lights | OK | Electric windows | OK |
| Brake lights | OK | Electric seats | NOT REPORTED |
| Parking lights | OK | | |

Comments on Electrical System:

All lights function as designed and the lenses are clear.

UNDER THE HOOD

OVERALL RATING: GOOD

| | |
|---------------|-----|
| Oil leaks | NO |
| Exhaust leaks | YES |
| Exhaust smoke | NO |

Comments on Interior:

Carpets are all dirty as well as having some rust stains in a few areas. The drivers side carpet has a whole approximately 4" round in it from wear. All the seats have several small rust stains on them. The rear storage area also has rust stains on some trim as well as the rear carpets. Under all of the seats the metal seat frames as well as the sliding seat tracks are rusted.

Road Test

ROAD TEST

OVERALL RATING: EXCELLENT

| | | | |
|--|----|--|----|
| Brake system - noise, vibration, effort | OK | Steering effort - drifting right or left | OK |
| Suspension - performance, noise, rough road test | OK | Transmission shift quality, smoothness, effort, slippage | OK |
| Idle | OK | Engine operating temperature | OK |
| Engine noise | OK | Transmission/Transaxle noise | OK |
| Acceleration | OK | CV joint/Drive axle noise | OK |
| Horn | OK | Parking brake operation | OK |
| Wind noise | OK | Engine performance | OK |
| Starting | OK | | |

Comments on Road Test:

I noticed a slight exhaust leak from the rear of this Rav4 upon start up. It sounded better as it warmed up. Maybe a small hole in the muffler???? The Toyota drove and handled very well with NO apparent issues at this time. As with any FLOOD vehicle this is subject to change DAILY.

Additional Inspection Points

ADDITIONAL INSPECTION POINTS

OVERALL RATING: EXCELLENT

| | | | |
|-------------------|----|------------------------|----|
| Door handles | OK | Door locks | OK |
| Gas door | OK | Keyless entry | OK |
| Grille | OK | Gas cap | OK |
| Tailgate/Liftgate | OK | Roof rack | OK |
| | | Evidence of smoke odor | OK |

Comments on Additional Inspection Points:

All additional inspection points checked out well. Please call your inspector Charlie at 215-480-1536 to further discuss how this FLOOD VEHICLE may affect the value and reliability going forward.